



OVERVIEW





Design SE-46C sensor

1. Threading for sensor bracket


2. Software numbers

X1 Ethernet

X2 Power supply and control signals

X3 Connector for operating device OI-TS

Dimension SE-46C sensor



1. Sensor field of view

2. Marking of viewing direction

3. Viewing area

4. Material web

5. Recommended distance from the material web to the sensor

6. The lower edge of the SE-46C must be aligned parallel to the material web.